

North of STA 45+00



South of STA 45+00



North of STA 50+00



South of STA 50+00



North of STA 55+00



South of STA 55+00



North of STA 60+00



South of STA 60+00



North of STA 65+00



South of STA 65+00



North of STA 70+00



South of STA 70+00



North of STA 75+00



South of STA 75+00



North of STA 80+00



South of STA 80+00



North of STA 85+00



South of STA 85+00



North of STA 90+00



South of STA 90+00



North of STA 95+00



South of STA 95+00



North of STA 100+00



South of STA 100+00



North of STA 105+00



South of STA 105+00



North of STA 110+00



South of STA 110+00



North of STA 115+00



South of STA 115+00



North of STA 120+00



South of STA 120+00




North of STA 125+00




South of STA 125+00


## **CEPRA Beach Monitoring Program:**

Surfside Beach: Site Photos
Post-Hurricane Harvey
11 Dec 2017





North of STA -10+00



South of STA -10+00



North of STA -5+00



South of STA -5+00



North of STA 0+00



South of STA 0+00




North of STA 5+00



South of STA 5+00



North of STA 15+00




South of STA 15+00



North of STA 20+00



South of STA 20+00



North of STA 25+00



South of STA 25+00



North of STA 30+00



South of STA 30+00



North of STA 35+00



South of STA 35+00



North of STA 40+00



South of STA 40+00



North of STA 45+00



South of STA 45+00



North of STA 50+00



South of STA 50+00



North of STA 55+00



South of STA 55+00



North of STA 60+00



South of STA 60+00



North of STA 65+00



South of STA 65+00



North of STA 70+00



South of STA 70+00



North of STA 75+00



South of STA 75+00



North of STA 80+00



South of STA 80+00



North of STA 85+00



South of STA 85+00



North of STA 90+00



South of STA 90+00



North of STA 95+00



South of STA 95+00




North of STA 100+00



South of STA 100+00


## **CEPRA Beach Monitoring Program:**

Sylvan Beach: Site Photos
Post- Hurricane Harvey
7 Dec 2017






North of STA 0+00



South of STA 0+00



North of STA 1+00



South of STA 1+00



North of STA 2+00



South of STA 2+00



North of STA 3+00



South of STA 3+00



North of STA 4+00



South of STA 4+00



North of STA 5+00



South of STA 5+00




North of STA 6+00




South of STA 6+00



North of STA 7+00




South of STA 7+00




North of STA 8+00



South of STA 8+00




North of STA 9+00



South of STA 9+00




North of STA 10+00



South of STA 10+00



North of STA 11+00



South of STA 11+00




North of STA 12+00



South of STA 12+00



North of STA 13+00



South of STA 13+00



North of STA 14+00



South of STA 14+00




North of STA 15+00



South of STA 15+00



North of STA 16+00



South of STA 16+00

## CEPRA Beach Monitoring Program:

Sylvan Beach: Damage Photos

Post-Hurricane Harvey

29 April 2017





